



TECHNICAL UPDATE DEVELOPMENT TOOLS MC68HC705JICS

Technical Update Development Tools contains updates to documented information appearing in other Motorola technical documents as well as new information not covered elsewhere.

We are confident that your Motorola product will satisfy your design needs. This Technical Update Development Tools and the accompanying manuals and reference documentation are designed to be helpful, informative, and easy to use.

Should your application generate a question or a problem not covered in the current documentation, please call your local Motorola distributor or sales office. Technical experts at these locations are eager to help you make the best use of your Motorola product. As appropriate, these experts will coordinate with their counterparts in the factory to answer your questions or solve your problems. To obtain the latest document, call your local Motorola sales office.


Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters can and do vary in different applications. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and  are registered trademarks of Motorola, Inc. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

TABLE OF CONTENTS

ICS05J1A

ICS05J1A Software	3
ICS05J1A Version 1.00 Bug List	3

CASM5J1A

CASM5J1A Software	5
CASM5J1A Version 1.00 Bug List.....	5

Addendum

Addendum to MC68HC705J1A HCMOS Microcontroller Unit Technical Data	8
---	---

TECHNICAL UPDATE DEVELOPMENT TOOLS

ICS05J1A

ICS05J1A Software

HC705JICS

Revision History

Date	Revision	Description
7/20/95	1.00	Includes tracker HC705JICS.001.

ICS05J1A Version 1.00 Bug List

Reference Document: Not applicable

Tracker Number: HC705JICS.001

Revision: 1.00

The bugs found in ICS05J1A version 1.00 have been corrected, and version 1.01 includes the changes. Version 1.01 can be found on the CSIC bbs through the following channels:

- WorldWideWeb: Set browser to URL:<http://freeware.aus.sps.mot.com/> and access the "68HC705J1A design contest" hotlink, then access the "new release" hotlink.
- FTP: ftp to [freeware.aus.sps.mot.com](ftp://freeware.aus.sps.mot.com) and get the file /pub/68hc05j/jics_101.zip.
- Dialup: Call (512)891-FREE, log onto CSIC bbs, go to 68hc05j directory of the files area and download the file jics_101.zip.

ICS05J1A version 1.00 bug list:

1. An asterisk (*) is not recognized as a parameter, but should be recognized as the address of the current opcode.
2. When LISTON and ZOOM commands are used together, the registers are displayed twice while stepping.

3. A command line parameter for COM port that is invalid locks the system.
4. Incorrect handling of PORTA interrupts. In this version, while interrupts are set to be positive-edge only and while one port A pin is held high, other port A pins transitioning to high can cause an interrupt. Normal operation is for one high PORTA interrupt pin to mask others because of the wired-OR architecture.
5. Clearing the IRQE bit in ISCR does not disable external interrupts.
6. If a parameter is used with the RESETGO command, the execution starts at that parameter. Execution should always start at the reset vector.
7. An external interrupt does not exit stop mode.
8. While executing code, a stop opcode exits to the debug window if the PC is hooked to the POD. The ICS05J1A should give a stop mode indicator and not return to the debug window prompt.
9. The verify command gives false positives.

CASM5J1A**CASM5J1A Software
HC705JICS****Revision History**

Date	Revision	Description
7/20/95	1.00	Includes tracker HC705JICS.002.

CASM5J1A Version 1.00 Bug List**Reference Document: Not applicable****Tracker Number: HC705JICS.002****Revision: 1.00**

The bugs found in CASM5J1A version 1.00 have been corrected, and version 1.01 includes the changes. Version 1.01 can be found on the CSIC bbs through the following channels:

- WorldWideWeb: Set browser to URL:<http://freeware.aus.sps.mot.com/> and access the "68HC705J1A design contest" hotlink, then access the "new release" hotlink.
- FTP: ftp to [freeware.aus.sps.mot.com](ftp://freeware.aus.sps.mot.com) and get the file /pub/68hc05j/jics_101.zip.
- Dialup: call (512)891-FREE, log onto CSIC bbs, go to 68hc05j directory of the files area and download the file jics_101.zip.

CASM5J1A version 1.00 bug list:

1. The TIMER reserved label is not recognized by the assembler.

MOTOROLA

Order this document by
MC68HC705J1AAD/D

SEMICONDUCTOR TECHNICAL DATA

Addendum to
MC68HC705J1A
HCMOS Microcontroller Unit
Technical Data

This addendum provides a correction and addition to the *MC68HC705J1A Technical Data* (Motorola document number MC68HC705J1A/D).

1. Page 4-5, **Figure 4-3. IRQ Status and Control Register** — Change as follows:

From:

	Bit 7	6	5	4	3	2	1	Bit 0
Read:	IRQE	0	0	IRQF	0	0	0	0
Write:				R			IRQR	
Reset:	1	0	0	0	0	0	0	0

= Unimplemented

 R = Reserved for factory test

Figure 4-3. IRQ Status and Control Register

To:

	Bit 7	6	5	4	3	2	1	Bit 0
Read:	IRQE	0	0	0	IRQF	0	0	0
Write:				R			IRQR	
Reset:	1	0	0	0	0	0	0	0


= Unimplemented

 R = Reserved for factory test

Figure 4-3. IRQ Status and Control Register

2. Page 4-6, section **4.6.2 Optional External Interrupts (PA0 through PA3)** — Add the following note:

NOTE: The $\overline{\text{IRQ}}$ pin has an internal Schmitt trigger. The optional external interrupts (PA0–PA3) do not have internal Schmitt triggers.

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters can and do vary in different applications. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and  are registered trademarks of Motorola, Inc. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

How to reach us:

USA/EUROPE: Motorola Literature Distribution; P.O. Box 20912; Phoenix, Arizona 85036. 1-800-441-2447

MFAX: RMFAX0@email.sps.mot.com – TOUCHTONE (602) 244-6609

INTERNET: <http://Design-NET.com>

JAPAN: Nippon Motorola Ltd.; Tatsumi-SPD-JLDC, Toshikatsu Otsuki, 6F Seibu-Butsuryu-Center, 3-14-2 Tatsumi Koto-Ku, Tokyo 135, Japan. 03-3521-8315

HONG KONG: Motorola Semiconductors H.K. Ltd.; 8B Tai Ping Industrial Park, 51 Ting Kok Road, Tai Po, N.T., Hong Kong. 852-26629298

