

N = 17474/002/00

This document was produced by SDC in performance of DOD SD 97

NOTE

an internal working paper

System Development Corporation/2500 Colorado Ave./Santa Monica, California

4/30

AUTHOR

Jack Slaybaugh
J. A. Slaybaugh

DATE

PAGE 1 OF 1 PAGES

26 April 1962

Author Delivered

U CODE - OTHER MODIFIER CONFLICTS - TAPE

For SLO (Tape) instructions, if the U modifier is set (i.e., backspace, set density, etc.), the RD-WR modifiers must not be set. The setting of the U modifier and read or write will cause an error interrupt and FIX does not return to the program.

Although this document contains no classified information it has not been cleared for open publication by the Department of Defense.

SDC INTERNAL DISTRIBUTION