



This Technical Advisory describes an issue which may or may not affect the customer's product

Intel Technical Advisory

TA-942-1

5200 NE Elam Young Parkway
Hillsboro, OR 97124

January 14, 2010

Update to Intel® Server Chassis SC5299UP, SC5299DP, SC5299BRP required to support Intel® Server Board S3420GP family

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The **Intel products described herein** may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Products Affected

Product Code	MM#	TA
SC5299BRP	877864 and earlier MM#	D46870-012 and earlier revision
SC5299BRPNA	881190 and earlier MM#	D46870-012 and earlier revision
SC5299DP	877875 and earlier MM#	D46866-011 and earlier revision
SC5299DPNA	880985 and earlier MM#	D46866-011 and earlier revision
SC5299UP	892757 and earlier MM#	D98044-004 and earlier revision
SC5299UPNA	893064 and earlier MM#	D98044-004 and earlier revision

Description

One 6-32# screw and four rubber pads have been added to the accessory kit of Intel® Server Chassis SC5299UP, SC5299DP and SC5299BRP to support the Intel® S3420GP series server boards.

Intel® Server Chassis has passed full scale validation on Intel® S3420GP series server boards with the additional **one 6-32# screw and four rubber pads**. The updated product support matrix for Intel® Server Chassis SC5299 family is:

Configuration	SC5299UP	SC5299DP	SC5299BRP	SC5299WS
Intel® Server Board Support	Intel® Server Board S3200SHV	Intel® Server Board S5000VSA	Intel® Server Board S5000VSA	Intel® Server Board S5000XVN
	Intel® Server Board S3210SHLC	Intel® Server Board S5000PSL	Intel® Server Board S5000PSL	
	Intel® Server Board S3210SHLX	Intel® Server Board S5000XSL	Intel® Server Board S5000XSL	
	Intel® Server Board S3420GPV	Intel® Server Board S3420GPLC	Intel® Server Board S3420GPLC	
		Intel® Server Board S3420GPLX	Intel® Server Board S3420GPLX	

Intel will provide free upgrade kit(s) (including one 6-32# screw and 4 rubber pads) to customers requesting them. If you need to get upgrade kit(s), please contact Intel using your normal warranty process, indicating that you are calling regarding TA-942-1. Have the following information when you call: the TA number(s) of the affected board(s), system(s) or chassis(s); and the MM#, Product Code and/or part number of the affected item needed.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division
Intel Corporation