

GDM-W900


SONY SERVICE MANUAL

US Model
Canadian Model
AEP Model
Chassis No. SCC-K49A-A



CORRECTION-1


File this supplement with the service manual.

SUBJECT : CORRECTION OF REPAIR PART

 : Indicates corrected portion

SECTION 7 ELECTRICAL PARTS LIST (See page 76)

Incorrect				Correct			
REF.NO.	PART NO.	DESCRIPTION	REMARK	REF.NO.	PART NO.	DESCRIPTION	REMARK
Q6400	8-729-927-09	TRANSISTOR	IRFI9630	 Q6400	8-729-035-89	TRANSISTOR	 2SJ449



997856291



9-978-562-91

Sony Corporation
Display Company
Quality Assurance Department
Service Promotion Section

English
97DL05202-1
Printed in Japan
© 1997.4